

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

MPP

Date: 12.03.10	Job No.: RD3405	ADR Yes/No: Y	ADR Date: 12.03.10	ECN #: 12- 545
Product No.: D412-704	Created By: RF	Approved By: #		
Product Name: Copilot's Emergency Cargo Release Kits	Checked By: #			

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL/MPP	
Purchasing Coord.	Y	CL	
Production Engineering Coord.	Y	EC/DD	

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	N		
Customer Technical Support	Y	MB/DS	
Marketing	N		
Customer Order Processing	N		

Reason for Change:	Revise Drawing per PAR12-162 feedback. Product Improvement
--------------------	---

Documents Affected:		
D412-704-041 Rev. B	D412-704-141 Rev. A	IIN-D412-704 Rev. C (DRAFT)
D3205 Rev. B	D3207 Rev. B	
D3208 Rev. B	D3257 Rev. B	
D4610 Rev. A	D4611 Rev. A	

PARTS MUST COMPLY

☐

PREVIOUS PARTS SATISFACTORY

☒

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	N			
6	Update Product Compatability Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	N	KJ		12.03.21
11	Update Product Specification Files	N			
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		12.03.21
13	Update Document Record (DR)	N			
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	Y	KJ		12.03.22
17	Update / Verify ARC Database	Y	KJ		
18	Create / Update Change Record Form / Item Card Database	Y	KJ	See below.	
19	Create / Update PPP's	Y	KJ		
20	Red Decals required?	Y	KJ	See below	
21	Update Document Control Database / Laminated Dwgs	Y	KJ		N/A
22	Update Grey Project / Electronic Binder PDF Files	N		Add ADR 412-704	
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		12.03.21
24					

Description / Action:	
Update BOM/routing for D412-704-011, D205-704-013, D3205 Rev. B, D3207 Rev. B, D3208 Rev. B, D3257 Rev. B, D4610 Rev. A and D4611 Rev. A	
Create BOM/routing for D412-704-015/-141	
D412-704-011 @ CHG 002; D205-704-013 @ CHG 002 - Done # 80267, 7860	
D412-704-015/-141 @ CHG 001; -015 Red Label required. - DWG	
Scrap the following parts is stock/current production: D3207-1/-2 per Rev. A, D3208-1/-7/-11 per Rev. A, D3257-1 per Rev. A	
D3205-1 Pedal Bracket per Rev. A can be used on D412-704-041 Pedal Assembly Rev. A	
D3205-3 Bracket Plate in stock/current production required to re-work per D3205 Rev. B to add the chamfer. - 82060	
D3207-3 per Rev. A, D3207-5 per Rev. A, D3208-3/-5 per Rev. A, parts ok as is.	
Update CNC program for D3257-1 per Rev. B N/A	
Build D412-704-015 kit for Eagle ASAP	
MDL/IIN/ICA to released after trial fit of D412-704-015 at Eagle.	

ECN Verified & Complete: _____ Date: _____